





## SCM 012 Torque




## SCM 012 Power






## SCM 017 Torque




## SCM 017 Power






## SCM 025 Torque




## SCM 025 Power






## SCM 034 Torque




## SCM 034 Power






## SCM 040 Torque




## SCM 040 Power






## SCM 047 Torque




## SCM 047 Power






## SCM 056 Torque




## SCM 056 Power






## SCM 064 Torque




## SCM 064 Power








## SCM 084 Torque




## SCM 084 Power






## SCM 090 Torque




## SCM 090 Power






## SCM 108 Torque




## SCM 108 Power





## SCM 130 Torque



## SCM 130 Power

